



## CODIGOS DE REEMPLAZO

ECOFILTER	REEMPLAZO MANN	REEMPLAZO FRAM	REEMPLAZO WEGA	REEMPLAZO BALDWIN	REEMPLAZO DONALDSON	REEMPLAZO FLEETGUARD
E75135R16	WK842/2/WK723	P4183/P5322	FCD-2058	BF587/BF5587	P550588/P550248/P550587	FF5156/FF5135
E93135R16	WK842/2	P4183/P5322	FCD-2058	BF587/BF5587	P550588/P550248/P550587	FF5156/FF5135
E93135R114	WK940/24	PS6643/PS8185	FCD-3026	BF46026/BF9622	P550088/P559306/P502516	FS1241/FS1247
E93135R20	WK940/11/WK9023	P4886/P10357	JFC-901/1/JFC-500	BF7534	P550390	FF5160
E93135R24	WK940/12	P5797/PS9422	FCD-2205	BF7624	P550495	FF5297
E93135R3/4	WK828	PS4922	JFC-215/JFC-503	BF7532/BF7533/BF7535	P550385	FF5159
E93180R13/16	WK940/7	P3401	FCD-2041	BF896	P551329	FF5038
E93180R16	WK950/19	PS10061	FCD-2099	BF1365	P550904	FS19821
E93180R114	WK950/3	P1104	FCD-2040	BF7633/BF970	P551313/P557440	FF185/FF5320/FF5814
E93180R20	WK950/21	P9454	FCD-2098	BF7813/BF7940/BF7957	P550881	FF5420/FF5421
E93220R112	WK962/13	FT6217	FCD-2209	BF1213/BF1342	P551523/P558010	FS1213/FS1243
E93220R114	WK950/26/WK940/1	PS6829/PS10713	FCD-2230	BF1259/BF1212	P553211/P555001	FS1242/FS1215
E93220R116	WK10002/2	PS12225	FCD-30126			
E108200R112	WK1060/7/WK1060/8	PS10037/PS9026/PS8187	FCD-3090/1/	BF46109	P502461	FS20041
E108200R114	WK1040/WK1060/3	PS9025/PS7171/PS9028	FCD-3060/FCD-3090/2	BF1346/BF1360	P551034/P551856	FS19932/FS19532
E108220R112	WK1060 C/SENS/PF420					
E108220R114	WK1060/1 C/SENS			BF1346-SP/BF1360-SP	P551065	
E108260R112	WK1060/WK1060/4	PS10610	FCD-2203/FCD-30120	BF46071	P551086	
E108260R114	WK1060/1	PS12127	FCD-3091/3	BF1363	P551026	FS19934

ANTE CUALQUIER DUDA O CONSULTA [ECOFILTERARGENTINA@GMAIL.COM](mailto:ECOFILTERARGENTINA@GMAIL.COM)